



# Tipping Sensor Assembly and Installation Guideline






## 1. Install Batteries

Install the 3x Lithium batteries in the correct direction.




## 2. Place The Cover

Put the back cover on, lining it up with the Oyster3 markings on the same side of the sensor.



### 3. Seal The Sensor

Fasten all 6 screws into the casing to seal the sensor.



#### 4. Locate A Vertical Surface

Locate a vertical surface that is flat and near the top of the load bin.

#### 5. Attaching The Surface

Thoroughly clean the surface and ensure it is dry before attaching the sensor, using the adhesive tape provided.

#### 6. Fixing The Sensor

The sensor has a red arrow on it, when fixing the sensor, this arrow should always face upwards to the sky.















